



REF D x L	L	M	d1	D	L2
<b>FT 12-15</b>	15	M5	7	12	7
<b>FT 20-21</b>	21	M6	13	20	9
<b>FT 20-31</b>	31	M6	13	20	19
<b>FT 25-21</b>	21	M6	16	25	8
<b>FT 25-31</b>	31	M6	16	25	18
<b>FT 25-41</b>	41	M6	16	25	28
<b>FT 32-30</b>	30	M8	20	32	14
<b>FT 32-50</b>	50	M8	20	32	34
<b>FT 42-30</b>	30	M8	30	42	12
<b>FT 42-50</b>	50	M8	30	42	32



REF D x L	L	L1	M	d1	D
<b>MT 12-15</b>	15	7	M5	7	12
<b>MT 20-21</b>	21	11	M6	13	20
<b>MT 20-31</b>	31	11	M6	13	20
<b>MT 25-21</b>	21	12	M6	16	25
<b>MT 25-31</b>	31	12	M6	16	25
<b>MT 25-41</b>	41	12	M6	16	25
<b>MT 32-30</b>	30	15	M8	20	32
<b>MT 32-50</b>	50	15	M8	20	32
<b>MT 42-30</b>	30	17	M8	30	42
<b>MT 42-50</b>	50	17	M8	30	42



REF	d1	d2	K	for
<b>AGS 12</b>	5,5	16	5	<b>FT 12 / MT 12</b>
<b>AGS 20</b>	6,6	25	5	<b>FT 20 / MT 20</b>
<b>AGS 25</b>	6,6	30	5	<b>FT 25 / MT 25</b>
<b>AGS 32</b>	9,0	37	6	<b>FT 32 / MT 32</b>
<b>AGS 42</b>	9,0	47	6	<b>FT 42 / MT 42</b>